

F. No. NIPGR/Engg./5/5/2016-17/

Dated: 13.04.2016

CORRIGENDUM

SUB.: A.M.C. of Split / Window type Air-conditioning units & water coolers installed at NIPGR Campus, New Delhi, during the year 2016-2017 and material required for day to day maintenance.

The tender invited vide Tender Id No. 2016_MST_100546_1 dated 31.03.2016 has following correction:

“The Appendix – ‘B’ i.e. list of spares in Financial Bid has been modified”

All other conditions remain unaltered.

सलाहकार अभियंता

Schedule of Quantity

Name of work: A.M.C. of Split / Window type Air-conditioning units & water coolers installed at NIPGR Campus, New Delhi, during the year 2016-2017 and material required for day to day maintenance.

B.

LIST OF SPARES (if & when required)

S. No	Description	Unit	Qnt	Rates	Amount	Make		
1	Compressor for Split A/C 1.0 TR	No	2			Kirloskar/Hitachi/Voltas/Existing		
2	Compressor for Split A/C 1.5 TR	No	4			Kirloskar/Hitachi/Voltas/Existing		
3	Compressor for Split A/C 2.0 TR	No	3			Kirloskar/Hitachi/Voltas/Existing		
4	Compressor for Window A/C 1.5 TR	No	1			Kirloskar/Hitachi/Voltas/Existing		
5	Compressor for Water Cooler	No	1			Kirloskar/Hitachi/Voltas/Existing		
6	Gas Charging in Split/window/watercooler	Kg	49			Kirloskar/Hitachi/Voltas/Existing		
7	Running Capacitor for Split AC/Window AC/Water Cooler	No	9			Apcos/ Genco/ ISI		
8	PTC Relay	No	2			L & T / Seimens		
9	Contactora	No	3			L & T / Seimens		
10	Accumulator	No	1			as per actual installations		
11	Overload Relay	No	1			L & T / Seimens		
12	Capillary & Filter	No.	5			as per actual installations		
13	Rewinding of Motor (Aluminium winding)	No.	10			As per directions of E.I.C		
14	Repairing of Remote PCB	No.	4			As per directions of E.I.C		
15	Repair of Auto Electronic Controller/ Voltage stabilizer	No	2			As per directions of E.I.C		
16	Repairing of Temperature Controller	No	1			As per directions of E.I.C		
17	Repairing of Humidity Controller	No	1			As per directions of E.I.C		
18	Repairing of Switching Unit	No.	1			as per actual installations		
19	Supply of Temperature Controller	No.	1			as per actual installations		
20	Supply of Humidity Controller	No.	1			as per actual installations		
21	Supply of Switching Unit	No.	1			As per directions of E.I.C		
22	Supply of New Condensor Fan for Split / Window AC	No	8			as per actual installations		
23	Supply of New Blower fan for Split/Window AC	No	1			as per actual installations		
24	Supply of new remote for split / window / cassette a.c.	No.	1			as per actual installations		
	TOTAL (B)							
	GRAND TOTAL (A+B)							

Seal & Signature of Contractor